



PRODUCT QUALITY BULLETIN

#570

NAPA Fuel Filter 400054:
Incorrect seal

08/18/2026

NAPA Fuel Filter	Total Quantity Shipped:	Affected Date Codes:
400054	861 Units	All

ISSUE SUMMARY:

Filter is supplied with the incorrect seal. The correct seal should be square cut.


REQUIRED ACTION:

If this issue is identified on your part, please dispose of the incorrect seal and contact your local representative to order seal # 50186-SEAL.


QUESTIONS OR ASSISTANCE:

If you have any questions or need help coordinating the return, please contact our product support team.

We apologize for any inconvenience and appreciate your prompt attention to this matter.



INCORRECT O-RING



CORRECT GASKET