PRODUCT QUALITY BULLETIN

#587

NAPA Fuel Filter 3063:
Incorrect Thread and Seat.

10/27/2026

NAPA Gold Fuel Filter	Total Quantity Shipped*	Affected Date Codes*	
3063	14,651 Units	24MHM25 10300 25MLJ03 10300 25MRS09 10300 25MRO24 10300	25MRN22 10300 25MRD14 10300 26MYM04 10300 26MTA10 10300

ISSUE SUMMARY

A fitment issue has been identified that may prevent the filter's threaded connection from seating properly during installation. The investigation documented fitment and leakage complaints and identified the geometry around the threaded fuel-line seating area as a concern.

REQUIRED ACTION

1. Check all stock of NAPA 3063 Fuel Filter with affected date codes and remove from active stock.
2. Quarantine affected inventory to prevent shipment or installation.
3. Do NOT sell or install the product as it can lead to fuel leaks.
4. Submit VDM or credit request through your standard channels.
5. Destroy the product after credit is issued or return to DC for destruction.

QUESTIONS OR ASSISTANCE:

If you have any questions or need help coordinating the return, please contact our product support team. We apologize for any inconvenience and appreciate your prompt attention to this matter.

* An issue was identified with the first date code listed above. As a precautionary measure, all inventory bearing the listed date codes should be pulled from stock and destroyed/returned to prevent any potentially affected products from being sold.