PRODUCT QUALITY BULLETIN

#473

NAPA Fuel Filter 3993:
Filter design error

10/20/2026

NAPA Fuel Filter	Total Quantity Shipped:	Affected Date Codes:
3993	1,719 Units	25MYF19 11767 25MHM31 11767 25MHM31 11767 25MEJ06 11767 25MTA05 11767

ISSUE SUMMARY:
Filter design error not allowing the filter to install into the housing.

- Filter cannot be locked into the housing.



REQUIRED ACTION:
If any of these date codes are identified on your part, please dispose of the part and contact your local representative to initiate the standard credit procedure.

QUESTIONS OR ASSISTANCE:
If you have any questions or need help coordinating the return, please contact our product support team.

We apologize for any inconvenience and appreciate your prompt attention to this matter.