PRODUCT QUALITY BULLETIN #546

NAPA Air Filter 9801:
Filter design error

NAPA Air Filter	Total Quantity Shipped:	Affected Date Codes:
9801	1,200 Units	24MRS27 11767 24MRD22 11767 25MLA17 11767 25MYM04 11767 25MYM14 11767 25MEJ27 11767

ISSUE SUMMARY:
Filter has incorrect design preventing installation.

REQUIRED ACTION:
1) Please dispose of the part and contact your local representative to follow the standard credit process.

QUESTIONS OR ASSISTANCE:
If you have any questions or need help coordinating the return, please contact our product support team.

We apologize for any inconvenience and appreciate your prompt attention to this matter.

