



PRODUCT QUALITY BULLETIN

#463

NAPA 501221:
Breather Filter

Part Number	Product Type	Affected Date Codes	Total Qty Shipped
501221	Breather Filter	25MYJ022184 25MLA252184	2,061 Units

Issue Summary:

Due to a production-related issue, some units of breather filter NAPA 501221 may exhibit excessive restriction to airflow. This condition can lead to engine performance problems such as:

- Vehicle entering limp mode
- Activation of the check engine light

Required Action:

Please dispose of the part and submit a request for VDM credit.

Questions or Assistance:

If you have any questions or need help coordinating the return, please contact our product support team.

We apologize for any inconvenience and appreciate your prompt attention to this matter.