



WRONG SIZE FILTER NOTICE

#560

NAPA Gold Oil Filter 100454:
Incorrect filter diameter identified in field inventory

06/25/2026

NAPA Oil Filter	Correct Size	Issue	Quantity Affected	Date Codes Affected
100454	3 3/4" Diameter	Incorrect filter diameter	10,200 units*	All ending in 3470

- The filter with a 3" diameter is the wrong size.
- Two different diameter filters for part number 100454 have been identified in the field.
- The filter with a 3 3/4" diameter is the correct specification and will be the standard going forward.
- Please inspect your inventory of part number 100454 and identify any filters with a 3" diameter.
- Although the 3" filter is smaller in overall size, all critical specifications are identical, and if already installed, it will fit and function properly with no need for vehicle recall.
- Please destroy any 3" diameter filters and submit a request for VDM credit or replacement with the correct 95mm filter.



* Total quantity affected. Many units were identified before shipping.