



PRODUCT QUALITY BULLETIN

#576

NAPA Oil Filter 1271:
Filter design issue

08/18/2026

NAPA Oil Filter	Total Quantity Affected	Affected Date Codes
1271	315 Units	25MYF19 11767 25MTA12 11767 25MTA16 11767

ISSUE SUMMARY:
Filter ID is too small, not allowing installation.

REQUIRED ACTION:
If these date codes are identified on your part, please dispose of the part and contact your local representative to initiate the standard credit procedure.

QUESTIONS OR ASSISTANCE:
If you have any questions or need help coordinating the return, please contact our product support team.

We apologize for any inconvenience and appreciate your prompt attention to this matter.

