PACKAGING ERROR

#588

NAPA Transmission Filter Kits
1-4558, 1-7057, 1-8594, 1-8567:
Transmission Filter Kits Shipped with Gasket Only and No Filter

10/26/2026

Due to a packaging error, some kits for the part numbers below shipped with a gasket only and no filter. These kits are incomplete and should not be sold.

AFFECTED PART NUMBERS:

1-4558	1-7057	1-8567	1-8594

WHAT TO DO:
Open each box of these part numbers in your inventory. Boxes with a filter and gasket are good and can go back on the shelf. Boxes with only a gasket should be scrapped. Submit a VDM credit request for the scrapped quantity of each part number and reference this TSB.







